



**Board of Civil Aviation
Sweden**

SAD No 1-003

SWEDISH AIRWORTHINESS DIRECTIVES

Section 1. Swedish manufactured Aeronautical Products

AIRWORTHINESS DIRECTIVE No 1-003

AIRCRAFT TYPE: SAAB-FAIRCHILD 340A

SERIAL No:s AFFECTED: 340A-004 and up

SUBJECT:

- Modification of Compressor Rotor Assembly and Actuating System Linkage Assembly
- Adjustment of Power Lever Input to the HMU
- Introduction of Special Inspections

**REFERENCE DOCUMENT(S): SAAB-SCANIA AB Service Bulletin
SF 340-72-003**

**GENERAL ELECTRIC Service Bulletin
(CT7-TP) 72-35**

COMPLIANCE TIME: Before next flight

The actions contained in this directive and reference document(s)
have been classified as mandatory for aircraft on Swedish register.

Norrköping November 20, 1984

Board of Civil Aviation
Flight Safety Department

LFS 1984:13

L 1555-2

Mail address

S-601 79 NORRKÖPING

Office address

Vikboplan 11

Telephone No

Nat 011 - 19 20 00
Int + 46 11 - 19 20 00

Directly

Mr Norén 19 20 62
Mr Hedblom 19 20 66

Cable address

Civilair
Norrköping

Telex address

64250