



**Board of Civil Aviation
Sweden**

SAD No 1-001

SWEDISH AIRWORTHINESS DIRECTIVES

Section 1. Swedish manufactured Aeronautical Products

AIRWORTHINESS DIRECTIVE No 1-001

AIRCRAFT TYPE: SAAB-FAIRCHILD 340A

SERIAL No:s AFFECTED: 340A-004 and up with parts stated in
below Service Bulletins installed

SUBJECT: Inspection and replacement of certain
parts affected by bad welding processes

REFERENCE DOCUMENT(S): SAAB-SCANIA AB Service Bulletins
SF 340-26-001; SF 340-36-001; SF 340-71-003
SF 340-71-004; SF 340-71-005.
All by revision 1.

COMPLIANCE TIME: In accordance with instructions in
the Service Bulletins.

The actions contained in this directive and reference document(s)
have been classified as mandatory for aircraft on Swedish register.

Norrköping 19 84-09-12

Board of Civil Aviation
Flight Safety Department

LFS 1984:10

L 1555-2

Mail address

S-601 79 NORRKÖPING

Office address

Vikboplan 11

Telephone No

Nat 011 - 19 20 00
Int + 46 11 - 19 20 00

Directly

Mr Norén 19 20 62
Mr Hedblom 19 20 66

Cable address

Civilair
Norrköping

Telex address

64250