
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Ändring av flyghandbok

GÄLLER: AS 350 B3

ÅTGÄRD: Utför åtgärder angivna i bifogad kopia av DGAC AD 1999-017-075(A)

TID FÖR ÅTGÄRD: Före flygning om ej tidigare utfört

UNDERLAG: DGAC AD 1999-017-075(A)
Flight Manual normal revision enligt punkt 3 i DGAC AD
1999-017-075(A)

REFERENS: DGAC AD 1999-017-075(A)

BESLUTSDATUM: 1999-01-29

LFS 1999:19

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.

Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Telegram	Telex
601 79 NORRKÖPING	Vikboplan 11	011-192000	Civilair Norrköping	62450

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 1999-017-075(A)
In case of any difficulty, reference should be made to the French original issue.

EUROCOPTER

AS 350 Helicopters

Climbing Speeds

1. EFFECTIVITY :

AS 350 B3 helicopters

2. REASONS :

This Airworthiness directive introduces new climbing speed curves. The currently applicable curves are resulting in values, the application of which might jeopardize the safety of operated helicopters.

3. MANDATORY ACTIONS AND COMPLIANCE TIME :

3.1. Before the first flight from the effective date of this Airworthiness Directive, the following actions are rendered mandatory :

- Replace page 9 section 5.1. (date code 97-40) of Flight Manual normal revision RN 0 with page 9 section 5.1 (date code 98-36) of conditional revision RC C.
- Replace page 9 of SUPPLEMENT 14 (date code 98-05) of Flight Manual normal revision RN 0 with page 9 of SUPPLEMENT 14 (date code 98-36) of conditional revision RC A.

3.2. The mandatory actions specified in paragraph 3.1. above are no longer applicable after embodiment of modifications 072803 and 072808 and introduction of Flight Manual normal revision RN 1 (date code 98.36) and normal revision RN 1 to SUPPLEMENT 14 (date code 98-36).

REF. : FLIGHT MANUAL

EFFECTIVE DATE :

On receipt from JANUARY 13, 1999

n/DJ

January 13, 1999

EUROCOPTER
AS 350 Helicopters

1999-017-075(A)