
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Byte av luftintagsfilter för motor

GÄLLER: Modeller och S/N med installerade filter angivna i bifogad kopia av FAA AD 99-05-09

ÅTGÄRD: Utför åtgärder angivna i FAA AD 99-05-09

TID FÖR ÅTGÄRD: Inom 25 flygtimmar räknat från den 25 mars 1999

UNDERLAG: FAA AD 99-05-09 och däri angivet underlag

REFERENS: FAA AD 99-05-09

BESLUTSDATUM: 1999-03-11

LFS 1999:47

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Telegram	Telex
601 79 NORRKÖPING	Vikboplan 11	011-192000	Civilair Norrköping	62450

Bilaga till LVD 2952

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39 - AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

AIRWORTHINESS DIRECTIVE

REGULATORY SUPPORT DIVISION
P.O. BOX 26460
OKLAHOMA CITY, OKLAHOMA 73125-0460

U.S. Department
of Transportation
**Federal Aviation
Administration**

The following Airworthiness Directive issued by the Federal Aviation Administration in accordance with the provisions of Federal Aviation Regulations, Part 39, applies to an aircraft model of which our records indicate you may be the registered owner. Airworthiness Directives affect aviation safety and are regulations which require immediate attention. You are cautioned that no person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of the Airworthiness Directive (reference FAR Subpart 39.3).

99-05-09 THE NEW PIPER AIRCRAFT, INC.: Amendment 39-11057, Docket No. 98-CE-110-AD.

Applicability: The following airplane model and serial numbers, certificated in any category, that are equipped with Purolator air filter part number (P/N) 638873, Model CA161PL, or Piper P/N 460-632 (PS60007-2):

Models	Serial Numbers
PA-23-235	27-505 through 27-622
PA-23-250	27-01 through 27-2504
PA-24-180 and PA-24-250	24-103 through 24-3687
PA-24-260	24-3642, and 24-4000 through 24-5028
PA-28-140	28-20000 through 28-7725290
PA-28-150, PA-28-160, and PA-28-180	28-1 through 28-7505259, and 28-E13
PA-28-181	28-7690001 through 28-8690062, and 2890001 through 2890205
PA-28-181	2890206 through 2890231, and 2843001 through 2843167
PA-28-235	28-10001 through 28-7710089, and 28-E11
PA-28-201T	28-7921001 through 28-7921095
PA-28R-201T	28R-7703001 through 28R-7803374
PA-28R-201T	2803001 through 2803012