

SWEDISH AIRWORTHINESS DIRECTIVES

Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS DIRECTIVE No: 1-006, Rev A

AIRCRAFT TYPE: SAAB-FAIRCHILD 340A

SERIAL No:s
AFFECTED: 340A-004 through -048

SUBJECT: FLIGHT CONTROLS - ALTERATION OF RUDDER LIMITER
HIGHER SPEED STOP

Analysis/tests have demonstrated that it is necessary to reduce the range of travel imposed by the rudder limiter mechanism in the higher speed range to fully comply with the certification requirements.

In addition, an inspection of the clearance of the limiter hook with the structure should also be performed.

REFERENCE
DOCUMENTS: SAAB-FAIRCHILD Service Bulletins
SF340-27-018 Rev 1 and SF340-27-032

COMPLIANCE TIME: The modification and inspection shall be incorporated not later than 31st October, 1985

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register.

Norrköping 1985-09-26

Board of Civil Aviation
Flight Safety Department

LFS 1985:24

Mail address

Office address

Telephone No

Directly

Cable address

Telex address

S-601 79 NORRKÖPING

Vikboplan 11

Nat 011 - 19 20 00

Int + 46 11 - 19 20 00

Mr Norén 19 20 62

Mr Hedblom 19 20 66

Civilair

Norrköping

64250