



LUFTFARTSVERKET
Luftfartsinspektionen

LUFTVÄRDIGHETSDIREKTIV (LVD)

A Motordrivna Luftfartyg
Skyvan
LVD Nr 2-3081

Sektion 2. Utlandstillverkad flygmateriel

TITEL: Kontroll av styrsystemets trimkablar och kedjor

GÄLLER: Skyvan SC7

ÅTGÄRD: Utför åtgärder angivna i bifogad kopia av CAA AD 011-04-2000

TID FÖR ÅTGÄRD: Ej senare än nästa 600 flygtimmars/6 månaders kontroll

UNDERLAG: Short Brothers Service Bulletin 27-76

REFERENS: CAA AD 011-04-2000

BESLUTSDATUM: 3 oktober 2000

LFS: 2000:119

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Faxnummer	Telegram Civilair	Telex
601 79 NORRKÖPING	Vikobplan 11	011-19 20 00	011-19 25 75	Norrköping	62450

CAA AIRWORTHINESS DIRECTIVE 011-04-2000

APPLICABILITY Short SC7 Skyvan aircraft.

SUBJECT - DESCRIPTION Flight Controls - To inspect flight control trim chains and cable/chain assemblies for manufacture using 'Spring Clip' connecting links.

COMPLIANCE - REQUIREMENT (SUMMARY) Compliance is required with Short Brothers Service Bulletin 27-76 not later than the next 600hr/6 month check. The Service Bulletin requires an inspection of all flight control trim chains and cable/chain assemblies to determine if the chain portion has been manufactured using 'Spring Clip' connecting link/s. If this type of link is fitted anywhere along the chain or cable/chain assembly, the chain or cable/chain assembly is to be replaced with a new assembly, without 'Spring Clip' connecting link/s fitted, not later than the following 600hr/6 month check. This action is required because a trim cable/chain assembly has been manufactured using 'Spring Clip' connecting link/s which does not meet the requirements of Class 1 locking.
