
Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS DIRECTIVE No: 1-031

AIRCRAFT TYPE: SAAB SF340A (SAAB-FAIRCHILD 340A)

SERIAL No:s AFFECTED: 340A-103 through -139

SUBJECT: Structure - Inspection of composite structure

BACKGROUND: A certain limited number of composite parts may contain delaminations as a result of technical difficulties encountered in production together with insufficiently recorded process documentation. Delamination and water intrusion could affect the structural integrity of the composite parts.

ACTIONS: Inspect composite parts as detailed in SAAB-SCANIA AB Service Bulletin SF340-51-006, dated February 10, 1989, or later revision. Report findings to SAAB-SCANIA AB in accordance with the bulletin.

COMPLIANCE TIME: Inspection to be performed at next A-check. In addition, until repair/replacement as detailed in the Service Bulletin has been performed, the inspection shall be included in the inspection after hard landings and flight in turbulent air as per AMM 05-50-00.

Norrköping 1989-02-13

LUFTFARTSVERKET
Flight Safety Department

LFS: 1989:5

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register.