
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Kontroll av magnetplugg och oljefilter

GÄLLER: SE 3160, SA 316B, SA 316 C, och SE 319 B med huvudrotoraxlar (alla P/N) som ej modifierats enligt MOD 072241

ÅTGÄRD: Utför åtgärder angivna i bifogad kopia av DGAC AD 98-304-058(A)

TID FÖR ÅTGÄRD: Enligt punkterna 3.1, 3.2, 3.3 i DGAC AD 98-304-058(A)

UNDERLAG: DGAC AD 98-304-058(A) och däri angivet underlag

REFERENS: DGAC AD 98-304-058(A)

BESLUTSDATUM: 1998-08-27

LFS 1998:55

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.

Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Telegram	Telex
601 79 NORRKÖPING	Vikboplan 11	011-192000	Civilair Norrköping	62450

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 98-304-058(A)
In case of any difficulty, reference should be made to the French original issue.

EUROCOPTER

SA 316/319 Helicopters

Main Gear Box

1. EFFECTIVITY

This Airworthiness Directive applies to SE 3160, SA 316B, SA 316C and SA 319B helicopters equipped with main gear boxes (MGB), all part numbers, which are not modified by MOD 072241.

2. REASON

This Airworthiness Directive is issued following bevel wheel gear attachment bolt failure which could lead to damage to the MGB and then the loss of the rotor drive.

3. MANDATORY ACTIONS AND COMPLIANCE

From the effective date of this Airworthiness Directive :

- 3.1. Carry out a daily check on the magnetic plug after the last flight of the day.
- 3.2. Check the oil filter every 25 hours.
- 3.3. Comply with the instructions given on work card 5.41.202 if the MGB oil is polluted.

REF. : Maintenance Manual :

- SE 3160 and SA 316B : Rush Revision No. 52A Date Code : 03-08
- SA 316C/319B : Rush Revision No. 17A Date Code : 03-98

EFFECTIVE DATE : AUGUST 08, 1998